Date:

Friday, 14/03/2008 10:50:27 AM

Linda Lacelle User: **Process Sheet** : FLOOR PROTCTOR FWD LH : CU-DAR001 Dart Helicopters Services Customer **Drawing Name** Job Number : 38018 **Estimate Number** : 11227 : D32811 **Part Number** P.O. Number S.O. No. : : D3281 REV B : 14/03/2008 **Drawing Number** This Issue : N/A Prsht Rev. : NC **Project Number** : THERMOFORMING : C : // First Issue Type **Drawing Revision** : 37888 Material **Previous Run** 7 Um: Each : 21/03/2008 Qty: Due Date Written By **Checked & Approved By** Comment : Est Rev:A 0407.01 New issue KJ/JLM Est. Rev B. 07.16.2007 Thermoform in house DL Est Rev C. 08.02.06 To reflect updated Dwg. DL **Additional Product** Job Number: Seq. #: **Machine Or Operation:** Description: 1.0 F6006 701 lexan black Comment: Qty.: 4.0000 sf(s)/Unit Total: 28.0000 sf(s) 107429 lexan black 2.0 HAND FINISH TH HAND FINISHING THERMOFORMING Comment: HAND FINISHING THERMOFORMING 1) Cut Blanks 3.0 THERMOFORMING Comment: THERMOFORMING MACHINE Thermoform as per Dwg. D32811and Folio FTA 011 Dwg. Rev. Folio Rev. QC2 4.0 PARTS AS THEY COME OFF MACHINE HAND FINISHING THERMOFORMING HAND FINISH TH 5.0

Comment: HAND FINISHING THERMOFORMING

1) Trim to Finished Dimensions


L. 08/03/24 ×7

Dart Aerospace Ltd


Dail Ac	ospace	5 Eta								
W/O:			V	VORK ORDER CHANG	ES					
DATE	STEP	PROCEDURE CHANGE					Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•						
					,					
Part No	:	PAR #:	_ Fault Ca	tegory:	_ NCR:	Yes N	lo DQ A	۸:	_ Date: _	
						QA: N/0	Closed	l:	Date:	
NCR:		W	ORK OR	DER NON-CONFORM	ANCE ((NCR)				
DATE	STEP	Description of NC	Corrective Action Section B			Veritication			Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
٠								!		

Date: Friday, 14/03/2008 10:50:27 AM User: Linda Lacelle **Process Sheet** Drawing Name: FLOOR PROTCTOR FWD LH Customer: CU-DAR001 Dart Helicopters Services Job Number: 38018 Part Number: D32811 Job Number: Seq. #: Description: **Machine Or Operation:** INSPECT PARTS AS THEY COME OFF MACHINE 6.0 QC2 Comment: INSPECT PARTS AS THEY COME OFF MACHINE 1) Check Surface finish for undesired marks, voids, dimples etc. 2) Check dimensions to ensure conformity to drawing tolerances. INSPECT WORK TO CURRENT STEP 7.0 QC5 Comment: INSPECT WORK TO CURRENT STEP PACKAGING RESOURCE #1 8.0 **PACKAGING 1 Comment: PACKAGING** RESOURCE #1 9.0 QC21 FINAL INSPECTION/W/O RELEASE Comment: FINAL INSPECTION/W/O RELEASE N08/03 U 08.03.26 Job Completion


Dart Ae	rospace	e Ltd							
W/O:		·	٧	VORK ORDER CHANGES				•	
DATE	STEP	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		-							
Part No		PAR #:	_ Fault Ca	tegory: NC	R: Yes	No DQA	·:	_ Date: _	
					QA: N/	C Closed	:	_ Date: _	
NCR:		W	ORK OR	DER NON-CONFORMANC	E (NCR)			
		Description of NC		Corrective Action Section B		Verifica	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Sectio		Chief Eng	QC Inspector
			į						
-									
								ŧ	



Dart Ae	rospace	Ltd							
W/O:			WC	RK ORDER CHANGES	,				
DATE	STEP	PR	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
ļ					• .				
Part No		PAR #:	Fault Cate	gory: N	NCR: Yes	No DQ	۸:	_ Date: _	
1					QA: I	N/C Closed	d:	_ Date: _	
NCR:			WORK ORDI	ER NON-CONFORMAN	CE (NCI	₹)			
D.47F	0750	Description of NC		Corrective Action Section B		Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8	Section		Chief Eng	QC Inspector
!									
I									
,								•	
:	1			· · · · · · · · · · · · · · · · · ·					
T									
								·	



Dart Ae	rospace	Ltd		•					
W/O:			W	ORK ORDER CHANGE	ES				
DATE	STEP	PRO	PROCEDURE CHANGE				Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				,				-	
:									
İ									
! .									
						, 			
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A :	Date:	
-1 -1 1					QA: N	I/C Close	d:	_ Date: _	
NCR:		V	VORK ORD	ER NON-CONFORMA	NCE (NCF	₹)	•		
		Description of NC	Corrective Action Section B			Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section Section		Chief Eng	QC Inspector
1							•		
!							,		
!									
1									
1									
1									



Dart Aerospace Ltd

D uit / (0	. oopao	o = (a								
W/O:			V	VORK ORDER CH	ANGES					
DATE	STEP	PROCEDURE CHANGE					Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
•				·				-		
Part No		PAR #:	Fault Ca	tegory:	NC	R: Yes	No DQ	A:	Date:	
	٠								Date: _	•
NCR:		V	VORK OR	DER NON-CONFO	RMANCE	E (NCR)		·	
DATE	STEP	Description of NC		Corrective Action	Section B	0: 0		cation	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Descrip Chief Eng	otion	Sign & Date	Secti	on C	Chief Eng	QC Inspector
				•						
•										
/					,					
	,									
	-									

DART AEROSPACE LTD	WORK ORDER:	38018
		*
Description: RYY FLOOR PROTECTOR FUD LIT	Part Number:	D3281-1
Inspection Dwg: からから Rev: C,		Page 1 of 1

FIRST ARTICLE INSPECTION CHECKLIST

First Article Prototype

(Step 4) Thermoforming Visual Inspection Sign-off

Description

Initials

Inside Radii less than 3/16" go/no go

Acceptable shape definition

Acceptable texture retention

Free of visual flaws (bumps, cracks, voids, etc.

(Step 6) Trimming FAI Checklist

Inspect dimensions highlighted on inspection sheet drawing ORQ Rev. and record below

Drawing	Tolerance	Actual	Accept	Reject	Method of	Comments
Dimension		Dimension			Inspection	
18.6	, 1	18.625	V			
17.1		17.1		<u> </u>		
11.7	030	0.963	~			
6,25	.030	0,163	√.		-	
·						
					•	· .
	· · · · · · · · · · · · · · · · · · ·					
					· ·	
Measured by:		Audited by:			Prototype Appro	val: A
Date: 08.0	3 24	Date:	1 095 CB J	4		
Rev Date	Change				Revised	by Approved
	New Issue	٠.				